

Jim Smith - Re: water monitoring

INCOMING 0015 0025  
dk

**From:** Mark Reynolds <mark.reynolds@cwmining.com>  
**To:** Jim Smith <jimdsmith@utah.gov>  
**Date:** 02/21/2007 1:13 PM  
**Subject:** Re: water monitoring

---

- 1) The small fault that was crossed in the main entries to the Hiawatha Seam in Mine #1
- 2) Plate 7-10b shows a floor seep as the Hiawatha workings approached the Blind Canyon
- 3) Mayo refers seep BP-1 in the "Direct interception of perched groundwater" section - a  
"We do not anticipate that partial dewatering of the Spring Canyon Sandstone will be
- 4) When were the T-1, -2, etc. bore holes drilled? Did Savage drill them their own use,

I'll probably have some more of these, but that will do for now.

Thanks again,

JIM

James D. SMITH  
[jimdsmith@utah.gov](mailto:jimdsmith@utah.gov)  
801 538 5262